

Coimisiún na Scrúduithe Stáit State Examinations Commission

Leaving Certificate Applied, 2004

Vocational Specialism – Engineering (240 marks)

Monday 14th June, 2004 Morning 9.30 a.m. – 11.00 a.m.

Sample solutions

	1 TO	α 1.1.
(+onoral	l Directions to	o (andidatos
CICILCI WI		Culluluulo

|--|

- 2. Answer all questions from Section 1.
- 3. Answer ANY THREE questions from Section 2.
- 4. Write your answers in the spaces provided and include sketches as appropriate.
- 5. Hand up this paper at the end of the examination.
- 6. If Question 7 is attempted, answer any two topics.

For the Superintendent only	For the Examiner only
Centre Stamp	1. Total of end of page totals
Contro Steamp	2. Aggregate total of all disallowed questions
	3. Total mark awarded (1 minus 2)
	4. Bonus mark for answering through Irish (if applicable)
	5. Total mark awarded if Irish Bonus (3 plus 4)
	Note: The mark in row 3 (or row 5 if Irish bonus is awarded) must equal the total mark on the flap at the end of the script.


Section 1 (90 Marks) Answer all three questions

1. 45 marks

Give brief answers to any fifteen of the following.


(Sketches may be used to explain your answers).

	QUESTION	ANSWER
(a)	State the name and use for part A.	Name_Split pin. UseTo prevent the nut from becoming loose. (2 + 1 marks)
(b)	If gear A is rotating as shown use arrows to show the direction of gears B and C.	A $(2 + 1 \text{ marks})$
(c)	What does this safety symbol indicate and where would it be used?	This indicates <u>Flammable substance.</u> Use <u>White spirits or other chemicals.</u> (2 + 1 marks)
(d)	Name the tool shown and state its use.	Tool_ Dot punch Use _To mark the centre of a hole before drilling. (2 + 1 marks)
(e)	Explain why stainless steel is used for making cutlery.	Reason _ It does not rust when exposed to water



QUESTION ANSWER (k) How is a Morse taper sleeve removed The application of a horizontal force to the drift from a drilling machine? by the hammer will knock out the morse taper. Morse taper sleeve. Drift (3 marks) (1) State one safety precaution that should Safety precaution Wear appropriate eye be observed when welding. protection. (3 marks) Name the machine tool shown and state (m) Name Drill chuck. its use. Use To hold a drill bit when using a drilling machine. (2 + 1 marks)(n) Why is a hand drill sometimes used Reason Electrical power may not be available instead of an electric drilling machine? (3 marks) (o) Name the electrical device shown. Name _Electric motor.

(3 marks)





Page 5 of 21

2. 25 marks

A pictorial view of a pipe bracket drawn full size is shown below.

(a) Complete the elevation and plan of the pipe bracket on the grid paper opposite.





(a) The diagram shows a person brazing. List **two** safety precautions observed and give a reason for each. One example is already listed.

 $(2 \times 2 + 1 \text{ marks})$

(2 marks)



Safety precaution	Reason
Example: An apron is worn.	To protect clothes from being burnt by sparks.
1. Eye protection is worn.	To prevent sparks entering the eyes
2. Protective gloves are worn.	To prevent the hands getting burnt.
(h) The diagram below shows a person using a	healtsony to out shoot motal. State a danger involved

(b) The diagram below shows a person using a hacksaw to cut sheet metal. State a danger involved in this process.

Danger The hacksaw may slip on the sheet


metal.

(c) When using the drilling ma	achine shown, identify a	ny two dangers and briefly describe the safety
precautions that should be	taken in each case.	$(2 \times 2 + 1 \text{ marks})$
Danger_Work not being held sec	urely	
Safety precaution Secure workpor clamp to the table.	iece in the drill vice	8
Danger_No eye protection worn.		
Safety precaution Ensure safety	glasses are being worn	
when drilling		
(d) State <u>two</u> safety precaution	s when using a lathe.	
Safety precaution 1Ensure safe	fety glasses are worn.	
Safety precaution 2 Chuck key i	must be removed before	
• •	must be removed before	0
starting centre lathe.	(2 2 1 1)	
	(2 x 2 marks each)	
(e) What does this safety syn	abol indicate and where	would it be used?
	(2 x 1 marks each)	A
Symbol indicates <u>High voltage.</u>		
Used Electrical poles.		4

Section 2 (150 Marks) Answer any three questions

4. 50 marks

The wall bracket is used to support a hanging basket for flowers. It is made from two pieces of steel, A and B that are welded together.




(a) Outline **any two** shortcomings with this design.

(2 x 10 marks each)

1 The overhang on part A is large and will require support

The holes in part b need to be countersunk to ensure screws fit flush with bracket



(a) Name <u>any five</u> par	ts of the engine shown.			A	1											
A Piston rings	E <u>Crankshaft</u>				,	ALL RINGS			В			C)		
B Piston	F Shell bearing	Н		000	6	The second			D			T			6	
C Camshaft	G Pully			200	6				1	R			Y			
D Conrod	H <u>Timing chain</u>		10	0							V	E 	_ <u>_</u>	F		_
					`(j			(5	5 x 4	m	arks	s ea	ach))	
•	s operate on the four-stroken of the induction and com	•					-		nes	-	ppr	opr	iat	e).		st.
Induction The piston starts	s at the top, the intake		1			$\overline{}$				1	Π		1	1		<u> </u>
valve opens and the pisto	n moves down to let the								1	+					#	
engine take in a cylinder-	full of air and gasoline.									+					+	
This is the intake stroke.									1						+	
						+	Н			+		\Box	\dashv	\dashv		
			-			+	\vdash		_	+		\Box	\dashv	\dashv		_
						+	Н			+				1		
Compression The valves	are closed and the piston		-			+	\vdash		\dashv	+	\vdash	\dashv	\dashv	\dashv	+	+
moves up to compress the	e fuel/air mixture.		_			+				\perp				4		
Compression makes the ex	xplosion more powerful.		+			+			_	+			\dashv	+	+	+
	1			\vdash	\vdash	+		\dashv	+	+		$\mid \mid \mid$	\dashv	\dashv	+	+
						1				\perp				\perp	\perp	
			-	\vdash	\vdash	+		\square	+	+		\square	\dashv	\dashv	+	+
		-	+	\vdash	\vdash	+	\vdash	\vdash	+	+	\vdash	H	\dashv	+	+	+
						士				\perp						
				$ \neg $				ΙΤ	Т				T	Т		

You are required to change the engine oil in a motorcar. Describe **four** steps necessary to (c) complete this procedure safely (use sketches as appropriate).

(4 x 4 marks each)



Step 1 Raise the car up.															_
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	<u> </u>			_	_	_	_	_	_	_				Ш	<u> </u>
														Ш	
Step 2 Get appropriate container and loosen the nut															
allowing the oil to drain out of the sump.															
anowing the on to train out of the samp.															
									Г					П	
Gran 2 Replace the nut on the sump								Г						П	Г
Step 3 Replace the nut on the sump.															
														П	
														П	
Step 4 Refill the oil and dispose of the old oil in an														П	
•														П	
appropriate way.														\Box	
akkrokrimea).									\vdash					\vdash	
	\vdash			\vdash	\vdash	\vdash				\vdash	\vdash			\vdash	
	\vdash	\vdash						\vdash	\vdash					\vdash	
	\vdash	\vdash					\vdash	\vdash	\vdash				\vdash	$\vdash\vdash$	
	1	1	I	I	I	I	I	I	1	I	I	1	. !	i I	i

6. 50 marks The bowl shown below is formed from a flat copper disk using a mallet and sandbag. Briefly (a) describe any two of the following processes used; annealing, cleaning and hollowing (use sketches as appropriate). (2 x 10 marks each) Mallet Copper bowl Sandbag Annealing This is used to soften the metal. Heat the copper and cool very slowly. Cleaning Clean the copper in a pickeling bath after annealing it. The pickeling bath contains acid. Hollowing Concentric circles are drawn. The copper is beaten with a bossing mallet on a leather sandbag. (b) List **two** safety precautions that should be observed during the annealing process. 1 Wear eye protection when heating.

2 Wear gloves when heating the workpiece.

(2 x 5 marks each)

		Point
		
		(2 x 4 marks each)
Mark out the length of point required.		
Thank out the length of point required.	_	
	_	
	-	
	-	
Heat the tip of the poker until red and hammer	_	
to shape using the anvil.	-	
	-	
d) Plastic dip coating is a suitable finish for the coating. tage 1 Clean the poker handle using emery paper		
tage 2 Heat the handle ensuring it does not become	me too hot.	

7. 50 marks

Systems Module

(Any two topics comprise a full module)

Answer any two from the following five topics.

Topic (a) – Computer Aided Design (CAD)

Topic (b) – Electricity

Topic (c) – Electronics

Topic (d) – Mechanisms

Topic (e) – Pneumatics

(a) A drawing of to produce the drawing and the drawing are the drawing and the drawing are th	_	one is shown. List any five CAD commands necessary to (5 x 3 marks each)
МОЕ	BILE	1 Draw.
	765432	2 Rectangle.
86) 8	3 Fillet.
		4 <u>Circle.</u>
(2)	i HJ	5 Ellipse
	the small shampoo bottl to draw the bottle B.	tle A using a CAD package, name the main command an (2 x 5 marks each)
	В	Command Scale.
		Procedure Select command. Select object to be
		scaled. Select ratio, select base point and enter.
A Q	Shampoo	
Shampoo		

(a) (1) Electric current can be supplied as AC or DC. What do these terms represent?

AC Alternating current.

(2 x 4 marks each)

DC Direct current.

(2) In what form is current supplied to our homes?


Alternating current (AC).

(1 x 4 marks)

- (b) Three wires A, B and C are to be connected to the ceiling rose below.
 - (1) Name the three wires.
 - A Live
 - B Neutral.

(3 x 3 marks each)

- C Earth.
- (2) Using the drawing below, connect wires A, B and C to the ceiling rose.




Name and give a use for **any four** of these electronic symbols and components. (a)



Name Bulb.

Use To provide light.



Name Push button switch.

Use To turn current on and off.



Name Capacitor

Use To store charge.

 $(4 \times 3 + 2 \text{ marks})$




Name _Toggle switch.

Use To turn current on and off. Use To vary the current flowing.



Name Variable resistor.




Name Resistor.

Use To reduce current.


(b) Part of a sensor circuit to control street lighting is shown below. State the name and use of **any two** of the following components.


(2+1) + (1+1) marks

Component	Name	Use
SW 1	Switch.	To turn current on and off.
LED	Light emitting diode.	To show current is flowing.
VR	Variable resistor	To vary current flowing.
LDR	Light dependent resistor.	Resistance depends on light.



(a) A load of 5N is acting downward 100mm from the fulcrum as shown below. Calculate the







Calculation $\underline{100 \times 5N} = \underline{200N} \times A$


200A = 500

A = 500/200 = 2.5N

(b) Identify <u>any two</u> of the mechanisms A, B or C and state where they are used.








 $(2 \times 3 + 3 \text{ marks})$

	Name	Where used
Mechanism A	Cam and follower.	Used in engine to open and close valves.
Mechanism B	Ratchet and pawl.	Used to tighten wire acting as a strainer.
Mechanism C	Pulley and vee belt	Drilling machines.

(a) Give a name and use for **any two** of the pneumatic symbols shown below.

 $(2 \times 3 + 2 \text{ marks})$



Name Single acting cylinder.

unic <u>- 8 - mar 8 - 5</u>

Use Testing frames in

engineering.

Name Tee connector.

Use To branch an airline in pneumatics.



Name Three-port valve.

Use To control the air flow in a circuit.

(b) A common type of pneumatic cylinder, controlled by a valve, is shown below.

(1) Name the type of cylinder shown.


Double-acting cylinder.

(2) Name the type of valve shown.

Five-port valve.

(3) Give a practical application of its use.

To open and close doors.



(c) Give **two** safety precautions when using compressed air.

(2 x 3 marks)

1 Always work at safe working pressures.

2 Never point a live airline at yourself or anybody else.
